

1 I hereby certify that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Rhonda Etienne

Rhonda Etienne

Date

2/6/06



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Serial No.: 10/662,645
Filed: September 15, 2003
Patent No.: 6,934,338 B1
Issued: August 23, 2005
Applicant(s): Moshe Bublil, Subroto Bose, Shirish C. Gadre, John Hong, Taner Ozcelik
Title: VARIABLE LENGTH DECODER FOR DECODING DIGITALLY ENCODED VIDEO SIGNALS

Certificates of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
FEB 13 2006
of Correction

**REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKES (37 CFR §1.322 (a)) AND
APPLICANTS' MISTAKES (37 C.F.R. §1.323)**

Sir:

Attached in duplicate form, is Form PTO-1050, with at least one copy being suitable for printing. Some of the errors below are (or may be contended to be) the mistake of Applicants who state that the errors are of a minor nature or character and occurred in good faith, and correction thereof does not involve such changes in the patent as would constitute new matter or would require reexamination. Some of the errors which appear on the Form PTO-1050 were

02/10/2006 TBESHAI1 00000026 6934338

01 FC:1811

100.00 OP

FEB 15 2006

typographical errors which occurred through the fault of the U.S. Patent and Trademark Office (“PTO”).

The exact column and line number where the errors are shown in the patent are as follows:

Page 1, Assignees reads “Sony Corporation, Tokyo (JP); Sony Electronics Inc., Park Ridge, NJ (US)” and should read – Sony Corporation, Tokyo (JP); Sony Electronics Inc., Park Ridge, NJ (US) – .

Page 2, OTHER PUBLICATIONS, reads “Patent Office, *PCT International Search Report Form PCT/ISA210*” and should read – Patent Office, *PCT International Search Report Form PCT/ISA/210* – .

Page 2, OTHER PUBLICATIONS, reads “...*A Fast Huffman Decoder*”, IEEE Transactions On Con [line break] sumer Electronics, US, IEEE Inc. New York, vol. 41, Feb. ...” and should read – ...*A Fast Huffman Decoder*”, IEEE Transactions On Con- [line break] sumer Electronics, US, IEEE Inc. New York, vol. 41, Feb. ... – . (missing the hyphen on Consumer at the line break)

Column 1, line 58 reads “...quantized chrominance and luminance pel values that are...” and should read – ...quantized chrominance and luminance pel values that are...–.

Column 2, line 3 reads “...pel blocks followed by quantization, zigzag scan, and...” and should read – ...pel blocks followed by quantization, zigzag scan, and...–.

Column 2, line 9 reads “The, I-frames are independently coded and are the least...” and should read – The I-frames are independently coded and are the least ...–.

Column 2, line 31 reads “...chrominance an luminance pel values. These values are then...” and should read – ...chrominance and luminance pel values. These values are then... –.

Column 5, line 36 reads “...subpicture, video information which may incorporate...” and should read – ...subpicture video information which may incorporate... –.

Column 5, line 57 reads “...each of he functional units in ASIC 100 via two main busses,...” and should read – ...each of the functional units in ASIC 100 via two main busses,... –.

FEB 15 2006

Column 6, line 61 reads "...which must be a parsed and decoded by video decoder 104..." and should read – ...which must be parsed and decoded by video decoder 104... –.

Column 8, lines 13-14 read, "...1/0", has 33 selectors to provide shifting to the left of 1 bits or no shift at all." and should read – ...1/0", has 33 selectors to provide shifting to the left of 1 bit or no shift at all. –.

Column 11, TABLE 2 reads, "vbi_mvfs1 0x08 1 r/w motion vertical field select one" and should read – vci_mvfs1 0x08 1 r/w motion vertical field select one –.

Column 11, TABLE 3 reads, "→00:8-bit, 01:9-bit, 10:10-bit" and should read – →00:8-bit, 01:9-bit, 10:10-bit, 11:11-bit –.

Column 11, TABLE 4 reads, "vci_dmvfifo_adr 0x23 3 r/w dmb_fifo read/write address" and should read – vci_dmvfifo_adr 0x23 3 r/w dmv_fifo read/write address –.

Column 13, TABLE 6 reads, "vld_pic_hdr r/w [31:0]] picture level params:" and should read – vld_pic_hdr r/w [31:0] picture level params: –.

Column 15, CLAIM 4, line 59 reads, "...the shift r circuit includes a plurality of selector circuits for..." and should read – ...the shifter circuit includes a plurality of selector circuits for... –.

Column 16, CLAIM 11, line 53 reads, "...unique prefix patterns, associated with the variable..." and should read – ...unique prefix patterns associated with the variable... –.

Column 16, CLAIM 11, line 56 reads, "...able length ncoded data to each of the plurality of..." and should read – ...able length encoded data to each of the plurality of ... –.

Please send the certificate to:

David H. Brinkman, Esq.
Wood, Herron & Evans, L.L.P.
2700 Carew Tower
441 Vine Street
Cincinnati, Ohio 45202

As some of the errors are, or could be contended to be Applicants' mistakes, enclosed is a check for \$100.00 to cover the correction fee. If there is any further charge or credit due, please use Deposit Account No. 23-3000.

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.

By: 

David H. Brinkman, Reg. No. 40,532

WOOD, HERRON & EVANS, L.L.P.
2700 Carew Tower
441 Vine Street
Cincinnati, Ohio 45202
(513) 241-2324

FEB 15 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,934,338 *B1*

DATED : August 23, 2005

INVENTOR(S) : Moshe Bublil, Subroto Bose, Shirish C. Gadre, John Hong, Taner Ozcelik

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Page 1, Assignees reads "Sony Corporation, Tokyo (JP); Sony Electronics Inc., Park Ridge, NJ (US)" and should read – Sony Corporation, Tokyo (JP); Sony Electronics Inc., Park Ridge, NJ (US) –.

Page 2, OTHER PUBLICATIONS, reads "Patent Office, *PCT International Search Report Form PCT/ISA210*" and should read – Patent Office, *PCT International Search Report Form PCT/ISA/210* –.

Page 2, OTHER PUBLICATIONS, reads "...*A Fast Huffman Decoder*", IEEE Transactions On Con [line break] sumer Electronics, US, IEEE Inc. New York, vol. 41, Feb." and should read – ...*A Fast Huffman Decoder*", IEEE Transactions On Con- [line break] sumer Electronics, US, IEEE Inc. New York, vol. 41, Feb. – . (missing the hyphen on Consumer at the line break)

Column 1, line 58 reads "...quantized chrominance and luminance pel values that are..." and should read – ...quantized chrominance and luminance pel values that are...–.

Column 2, line 3 reads "...pel blocks followed by quantization, zigzag scan, and..." and should read – ...pel blocks followed by quantization, zigzag scan, and...–.

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.
2700 Carew Tower
441 Vine Street
Cincinnati, OH 45202-2917

PATENT NO. 6,934,338
No. of add'l copies

@ 50¢ per page: _____

Page 1 of 3

FEB 15 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,934,338 *β1*

DATED : August 23, 2005

INVENTOR(S) : Moshe Bublil, Subroto Bose, Shirish C. Gadre, John Hong, Taner Ozcelik

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2, line 9 reads "The, I-frames are independently coded and are the least..." and should read – The I-frames are independently coded and are the least ... –.

Column 2, line 31 reads "...chrominance and luminance pel values. These values are then..." and should read – ...chrominance and luminance pel values. These values are then... –.

Column 5, line 36 reads "...subpicture, video information which may incorporate..." and should read – ...subpicture video information which may incorporate... –.

Column 5, line 57 reads "...each of the functional units in ASIC 100 via two main busses,..." and should read – ...each of the functional units in ASIC 100 via two main busses, ... –.

Column 6, line 61 reads "...which must be a parsed and decoded by video decoder 104..." and should read – ...which must be parsed and decoded by video decoder 104... –.

Column 8, lines 13-14 read, "...1/0", has 33 selectors to provide shifting to the left of 1 bits or no shift at all." and should read – ...1/0", has 33 selectors to provide shifting to the left of 1 bit or no shift at all. –.

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.
2700 Carew Tower
441 Vine Street
Cincinnati, OH 45202-2917

PATENT NO. 6,934,338
No. of add'l copies

@ 50¢ per page: _____

Page 2 of 3

FEB 15 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,934,338 *B1*

DATED : August 23, 2005

INVENTOR(S) : Moshe Bublil, Subroto Bose, Shirish C. Gadre, John Hong, Taner Ozcelik

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 11, TABLE 2 reads, “vbi_mvfs1 0x08 1 r/w motion vertical field select one” and should read – vci_mvfs1 0x08 1 r/w motion vertical field select one –.

Column 11, TABLE 3 reads, “→00:8-bit, 01:9-bit, 10:10-bit” and should read – →00:8-bit, 01:9-bit, 10:10-bit, 11:11-bit –.

Column 11, TABLE 4 reads, “vci_dmvfifo_adr 0x23 3 r/w dmb_fifo read/write address” and should read – vci_dmvfifo_adr 0x23 3 r/w dmv_fifo read/write address –.

Column 13, TABLE 6 reads, “vld_pic_hdr r/w [31:0]] picture level params:” and should read – vld_pic_hdr r/w [31:0] picture level params: –.

Column 15, CLAIM 4, line 59 reads, “...the shift r circuit includes a plurality of selector circuits for...” and should read – ...the shifter circuit includes a plurality of selector circuits for... –.

Column 16, CLAIM 11, line 53 reads, “...unique prefix patterns, associated with the variable...” and should read – ...unique prefix patterns associated with the variable... –.

Column 16, CLAIM 11, line 56 reads, “...able length ncoded data to each of the plurality of...” and should read – ...able length encoded data to each of the plurality of ... –.

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.
2700 Carew Tower
441 Vine Street
Cincinnati, OH 45202-2917

PATENT NO. 6,934,338
No. of add'l copies

@ 50¢ per page: _____

Page 3 of 3

FEB 15 2008

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 6,934,338 *B1*

DATED : August 23, 2005

INVENTOR(S) : Moshe Bublil, Subroto Bose, Shirish C. Gadre, John Hong, Taner Ozcelik

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Page 1, Assignees reads "Sony Corporation, Tokyo (JP); Sony Electronics Inc., Park Ridge, NJ (US)" and should read – Sony Corporation, Tokyo (JP); Sony Electronics Inc., Park Ridge, NJ (US) – .

Page 2, OTHER PUBLICATIONS, reads "Patent Office, *PCT International Search Report Form PCT/ISA210*" and should read – Patent Office, *PCT International Search Report Form PCT/ISA/210* – .

Page 2, OTHER PUBLICATIONS, reads "...*A Fast Huffman Decoder*", IEEE Transactions On Con [line break] sumer Electronics, US, IEEE Inc. New York, vol. 41, Feb. ..." and should read – ...*A Fast Huffman Decoder*", IEEE Transactions On Con- [line break] sumer Electronics, US, IEEE Inc. New York, vol. 41, Feb. ... – . (missing the hyphen on Consumer at the line break)

Column 1, line 58 reads "...quantized chrominance and luminance pet values that are..." and should read – ...quantized chrominance and luminance pel values that are...–.

Column 2, line 3 reads "...pet blocks followed by quantization, zigzag scan, and..." and should read – ...pel blocks followed by quantization, zigzag scan, and...–.

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.
2700 Carew Tower
441 Vine Street
Cincinnati, OH 45202-2917

PATENT NO. 6,934,338
No. of add'l copies

@ 50¢ per page: _____

Page 1 of 3

FEB 15 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,934,338 B1

DATED : August 23, 2005

INVENTOR(S) : Moshe Bublil, Subroto Bose, Shirish C. Gadre, John Hong, Taner Ozcelik

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2, line 9 reads "The, I-frames are independently coded and are the least..." and should read – The I-frames are independently coded and are the least ... –.

Column 2, line 31 reads "...chrominance and luminance pel values. These values are then..." and should read – ...chrominance and luminance pel values. These values are then... –.

Column 5, line 36 reads "...subpicture, video information which may incorporate..." and should read – ...subpicture video information which may incorporate... –.

Column 5, line 57 reads "...each of the functional units in ASIC 100 via two main busses..." and should read – ...each of the functional units in ASIC 100 via two main busses, ... –.

Column 6, line 61 reads "...which must be a parsed and decoded by video decoder 104..." and should read – ...which must be parsed and decoded by video decoder 104... –.

Column 8, lines 13-14 read, "...1/0", has 33 selectors to provide shifting to the left of 1 bits or no shift at all." and should read – ...1/0", has 33 selectors to provide shifting to the left of 1 bit or no shift at all. –.

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.
2700 Carew Tower
441 Vine Street
Cincinnati, OH 45202-2917

PATENT NO. 6,934,338
No. of add'l copies

@ 50¢ per page: _____

Page 2 of 3

FEB 15 2000

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,934,338 *Bi*

DATED : August 23, 2005

INVENTOR(S) : Moshe Bublil, Subroto Bose, Shirish C. Gadre, John Hong, Taner Ozcelik

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 11, TABLE 2 reads, “vbi_mvfs1 0x08 1 r/w motion vertical field select one” and should read – vci_mvfs1 0x08 1 r/w motion vertical field select one –.

Column 11, TABLE 3 reads, “→00:8-bit, 01:9-bit, 10:10-bit” and should read – →00:8-bit, 01:9-bit, 10:10-bit, 11:11-bit –.

Column 11, TABLE 4 reads, “vci_dmvfifo_adr 0x23 3 r/w dmb_fifo read/write address” and should read – vci_dmvfifo_adr 0x23 3 r/w dmv_fifo read/write address –.

Column 13, TABLE 6 reads, “vld_pic_hdr r/w [31:0]] picture level params:” and should read – vld_pic_hdr r/w [31:0] picture level params: –.

Column 15, CLAIM 4, line 59 reads, “...the shift r circuit includes a plurality of selector circuits for...” and should read – ...the shifter circuit includes a plurality of selector circuits for... –.

Column 16, CLAIM 11, line 53 reads, “...unique prefix patterns, associated with the variable...” and should read – ...unique prefix patterns associated with the variable... –.

Column 16, CLAIM 11, line 56 reads, “...able length ncoded data to each of the plurality of...” and should read – ...able length encoded data to each of the plurality of ... –.

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.
2700 Carew Tower
441 Vine Street
Cincinnati, OH 45202-2917

PATENT NO. 6,934,338
No. of add'l copies

@ 50¢ per page: _____

Page 3 of 3

FEB 15 2006